

application note

No. AP90501

Model 9050/9055 5-Slot Chassis Bracket Problem

Development System: MODEL 9050/9055

Production System: MODEL 9050/9055

Application:

Certain combinations of ISA boards have a potential fit problem when placed across from one another in these chassis. The edge of the card hold down bracket may interfere not allowing the board to be fully seated in the connector.

The solution in these cases is to cut the tab off of the hold down bracket for clearance. The bracket edge closest to the ISA connector on the board needs to be cut or trimmed about $\frac{1}{4}$ of an inch.

Note:

This will only have to be done on boards that do not fully seat, not all boards have this problem.